



Technical Repair Center 2017 Repair Pricing

**Please include a Repair Request form with all repairs.*

If you have any questions please feel free to contact us!

Divator MK II Annual Service

*Includes Annual Service Kit

Mask Only – With SP	\$118.00 parts (#300); \$65.00 Labor	\$178.91
Mask Only – Without SP	\$117.00 parts (#300NSP); \$65.00 Labor	\$178.22
Add: Gill Old Style	\$18.00 parts (#97220-01); \$32.50 Labor	\$50.00
Add: Hatch-New Style	\$21.80 parts (#460-190-710); \$32.50 Labor	\$53.70
Hatch Installed in	\$243.50 parts (#6316); \$15.00 Labor	
Low Volume Visor	*Visor & Hatch Only (#96962-01) \$243.50	\$258.50

*****For all mask repairs add: \$12.50 shop fee*****

Cold Water Rescue Suit Repairs	\$65.00 per hour plus parts	\$65.00+
Leak Test	\$32.50 labor	\$32.50

Communication Repairs	\$65.00 per hour plus parts	\$65.00+
------------------------------	-----------------------------	----------

Dry Suit Repairs

Shop Rate (Labor)	\$65.00 per hour plus parts	
#6388 Cuff Rings	\$105.00 parts; \$65.00 Labor	\$170.00
#2062 Viking Pro Cuff (each)	\$27.00 parts; \$32.50 Labor	\$59.50
Viking Pro Cuff (pair)	\$54.00 parts; \$65.00 Labor	\$119.00
#2063 Viking HD Cuff (each)	\$36.00 parts; \$32.50 Labor	\$68.50
Viking HD Cuff (pair)	\$72.00 parts; \$32.50 Labor	\$137.00
#2056 Viking Neck Seal	\$42.00 parts; \$65.00 Labor	\$107.00
#2045 Viking Surveyor Latex Hood	\$62.00 parts; \$65.00 Labor	\$127.00
Viking Nautic Hood	\$114.00 parts; \$65.00 Labor	\$179.00
Viking Smooth Skin Hood	\$135.00 parts; \$65.00 Labor	\$200.00
Viking Turbo Hood (M/L sizes)	\$315.00 parts; \$97.50 Labor	\$412.50
Viking Inner Hood Latex, Turbo (M/L sizes)	\$62.00 parts; \$97.50 Labor	\$159.50
Viking Magnum Hood (M/L/XL sizes)	\$295.00 parts; \$97.50 Labor	\$392.50
Viking Stretch Magnum Hood (M/L/XL sizes)	\$315.00 parts; \$97.50 Labor	\$412.50
Viking Hood Face Seal	\$62.00 parts; \$97.50 Labor	\$159.50
#2065 Viking Shoulder Zipper		
#2077 & Reinforcement Strip (STD 37")	\$294.00 parts; \$162.50 Labor	\$456.50
#2067 Viking Shoulder Zipper		
#2077 & Reinforcement Strip (HD 37")	\$389.00 parts; \$162.50 Labor	\$551.50
#2070 Viking Relief Zipper		
#2072 & Reinforcement Strip (STD; Red or Black Strip)	\$181.00 parts; \$97.50 Labor	\$278.50
#2024 Ocean Eye Latex Hood One Way Purge Valve	\$18.00 parts; \$16.25 Labor	\$34.25
#2126 Aqua Lung Polytex Hood One Way Purge Valve	\$15.00 parts; \$16.25 Labor	\$31.25

Phone: (800) 248-3483
Fax: (970) 482-0893

201 North Link Lane
Fort Collins, CO 80524

repairs@diverescueintl.com
www.diverescueintl.com



Technical Repair Center 2017 Repair Pricing

Leaking Test & Repair:

Leak Test	\$32.50 Labor
Leak Test (1-5 patch repair)	\$65.00 Labor
Leak Test (6-10 patch repair)	\$97.50 Labor
Leak Test (11-15 patch repair)	\$162.50 Labor

******* All Dry Suit Repairs Add: \$15.00 Shop Fee*******

Custom Repairs and Modifications:

For boot or pocket installations please call for a quote.

For DUI & Whites Suits: Please call and we can obtain an RA# to return directly to manufacturer.

For any other suit brands please call for more information regarding repairs.

*All repairs have a minimum of ½ hour labor charge (unless otherwise stated).
Labor is \$65.00/hour.

*******Shipping and Insurance will be added to all repair orders. To use a department or company account please call once repair has been shipped to Dive Rescue International*******